

Additional Funding Request

Site: NY023	WO# 16860 CSS #35254
Description of Repairs	Drain System, Replace High Pressure sensor and 1 ½ relief valve. Refill system and check operation
Diagnosis: Initial Work Order	Repair boiler in building #128
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	4 total man hours @ 235.00 hr = \$940.00
Additional Material Cost to Perform Repairs	\$495.00
Total Cost of Repair	\$1435.00

April 5, 2022



ESTIMATE 040422 CSS35254 WO16860

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO
Customer ID#	NY023 (BLDG 128)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
1	1	<p>NY23 BLDG128 (BOILER ROOM)</p> <p>DRIAN SYSTEM</p> <p>REPLACE HIGH PRESSURE</p> <p>SENIOR AND 1 1/2" RELIEF VALVE</p> <p>REFILL SYSTEM AND CHECK</p> <p>OPERATION</p> <p><u>MATERIAL</u></p> <p>HIGH PRESSURE SENSOR</p> <p>1 1/2" RELIEF VALVE</p> <p><u>LABOR</u></p> <p>4 HRS @ \$235.00</p> <p>TOTAL</p>		<p>\$495.00</p> <p>\$940.00</p> <p>\$1435.00</p>

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581