

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY23 Bldg 128 Date of Visit: 5/18/22

Location Address: FT TOTTEN

Contractor Personnel on Site:

JOHN S. STEVE SR

Work Performed: Replace sensor on Paden #1

Service Calls – PO/CSS#

CIS 35254 WO 16860

Please take pictures and send with quote

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: John Wolfe

Date: 5/18/22

Signed: John


To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site.

Print Name/Rank: Louis Camino RFS Date: 18 MAY 2022

Signed: Louis Camino

Email: Louis.m.Camino.CIV@Army.mil



B-1
DWG#TC1.6
B128



1015
ED.
PIEDS
ECTEUR
PLATE
TU/HR
KW
BTU/HR
KW
TIBLES
VENT: / 6"
EVENT: / 6"

NORM
WATE