

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: N4023-206

Date of Visit: 9/23/22

Location Address: Fort Totten, NY

Contractor Personnel on Site:

Deen Rowe (1SG)

Work Performed: g Put on operator to fault to decrease pressure / found leak because of drain pipes, replaced to stop leak.

Service Calls - PO/CSS#

CSS#89972 corrected css is 89973


Please take pictures and send with quote

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Deenvaughn Rowe

Date: 9/23/22

Signed: 

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site.

Print Name/Rank: P COMITO AFWS

Date: 9.23.22

Signed: 

Email: PETER, D. COMITO, CTR

