

### CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: N4023 - Building 330

Date of Visit: 11/7/22

Location Address: Fort Totten

Contractor Personnel on Site:

Deen Row

Work Performed: g Installed filter in water supply line / reinstall drain of water fountain.

Service Calls – PO/CSS# 90599

**Please take pictures and send with quote**

### CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Deen Vaughn Row

Date: 11/7/22

Signed: Deen Vaughn Row

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site.

Print Name/Rank: P CORN TO

Date: 11.03.22

Signed: P CORN TO

Email: PETER.D.COMPTO.CORNARMY.MIL

