

## Additional Funding Request

<b>Site: NY023</b>	<b>WO# 19770 CSS #90635</b>
Description of Repairs	11/3 Acav performed a diagnostic, determining this is not a mechanical issue but power to the reader. 11/3 Dispatched to Locurrent. To include diagnostic and repair if possible on MEP Gate NTE
Diagnosis: Initial Work Order	MEP lot man gate repair
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	X2 men @ 8hours @ 85.00=1360.00 Acav diagnostic Fee 450.00 Total 1810.00
Additional Material Cost to Perform Repairs	
Total Cost of Repair	1810.00

LoCurrent Systems, LLC  
3522 County Highway 11  
Cooperstown, NY 13326  
(607)293-7300  
locurrent@gmail.com



Estimate

ADDRESS  
ISG International Support Group

ESTIMATE # 2123  
DATE 11/04/2022

P.O. NUMBER  
Totten MEP Lot Man Gate Repair

ACTIVITY	QTY		AMOUNT
<b>Services</b>	1	1,360.00	1,360.00
Ft. Totten, NY023			
WO#19770 CSS#90635			
Diagnose/Repair if Possible MEP			
Lot Man Gate			

Dear Ms. Dubois:

As per your request, LoCurrent Systems is pleased to provide a quotation to Diagnose/Repair if Possible MEP Lot Man Gate at the Ft. Totten, NY023 Facility.

Cost Breakdown:

(2) men 8 hours @  
\$85/hr.....\$1,360.00

The cost for the above mentioned work is \$1,360.00.

If acceptable, please do not hesitate to contact us so that we may schedule for work to be completed.

Thank you so much for thinking of LoCurrent Systems

Sincerely,

Antonietta LoRusso

TOTAL

**\$1,360.00**

Accepted By

Accepted Date

# ACAV SERVICES

November 3, 2022



## INVOICE 110322A CSS90635 WO19770

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO
Customer ID#	NY023 (MEP)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
		<b>NY23 (MEP)</b> <b>MEP GATE NOT WORKING</b> <b>DIAGNOSED MECHANICAL</b> <b>OPERATION AND FOUND A</b> <b>SHORT BETWEEN THE POWER</b> <b>SUPPLY AND THE CARD READER</b> <b>THE VENDOR THAT REPAIRS THE</b> <b>CARD READER WILL HAVE TO BE</b> <b>CALLED</b>		
		<b><u>LABOR</u></b> <b>2 HRS @ \$225.00</b>		<b>\$450.00</b>
		<b>TOTAL</b>		<b>\$450.00</b>

### ACAV Services

11 Snug Cove Lane  
Bayville NY 11709  
Jacka377@verizon.net  
516 941 6581

### CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY 23 MEP Core

Date of Visit: 11/3/22

Location Address: FT TOTTEN

Contractor Personnel on Site:

PAUL JAHN

Work Performed: MEP CORE NOT WORKING NO POWER TO  
CAND BEAM

Service Calls – PO/CSS#

CSS 90635 NO 14770

Please take pictures and send with quote

### CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: JOHN WOHLE

Date: 11/3/22

Signed: [Signature]

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site.

Print Name/Rank: LOUIS GARCIA RFOS

Date: Nov 3, 2022

Signed: [Signature]

Email: LOUIS.GARCIA.CIV@ARMY.MIL



