

## CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: N4023 - Building 123

Date of Visit: 11/10/22

Location Address: Fort Totten

Contractor Personnel on Site:

Deen Row

Work Performed: g Replaced Diesel fuel Pump Vacuum Breaker, fuel pump no longer leaking when pumping fuel.

Service Calls - PO/CSS# 90683

**Please take pictures and send with quote**

## CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Deen Vaughn Row

Date: 11/10/22

Signed: Deen Vaughn Row

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site.

Print Name/Rank: P CORN 20

Date: 11.10.22

Signed: P CORN 20

Email: PETER.D.CORN@US.ARMY.MIL

