

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY023 - 200

Date of Visit: 12/7/22

Location Address: Fort Totten

Contractor Personnel on Site:

Deen Row

Work Performed: g Repair Chiller leak to restore heating/cooling
in 100m.

Service Calls - PO/CSS#

91068 corrected CSS 91126

Please take pictures and send with quote

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Deen Vaughn Row

Date: 12/7/22

Signed: Deen Vaughn Row

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site.

Print Name/Rank: P CORN 20

Date: 12-7-22

Signed: P CORN 20

Email: PETER.D.CORNZO.CORNZO@ARMY.MIL

