

## Additional Funding Request

<b>Site: NY023</b>	<b>WO#20231 CSS # 91163</b>
Description of Repairs	Install government-supplied radiator, drain system, cut out spud, install new radiator with new spud, and recharge unit. Check for proper operation
Diagnosis: Initial Work Order	building 330A 2nd floor room 204 connect radiator
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	1250.00
Additional Material Cost to Perform Repairs	150.00
Total Cost of Repair	\$1400.00

# ACAV SERVICES

December 28, 2022



## ESTIMATE 122822 CSS91163 WO20231 ESTIMATE

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO
Customer ID#	NY023 (BLDG 330A)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
		<b>NY23 (BLDG 330A) (ROOM 204)</b>  <b>INSTALL GOVERNMENT SUPPLIED 1 EA RADIATOR</b> <b>DRIAN SYSTEM</b> <b>CUT OUT SPUD</b> <b>INSTALL RADIATOR WITH NEW SPUD</b> <b>RECHARGE SYSTEM</b>  <b><u>MATERIAL</u></b> <b>1 1/4 ' COUPLING</b> <b>1 1/4 SPUD</b>		\$150.00

### ACAV Services

11 Snug Cove Lane  
Bayville NY 11709  
Jacka377@verizon.net  
516 941 6581

Qty.	Item#	Description	Unit Price	Line Total
		<b><u>LABOR</u></b> <b>5 HRS @ \$250.00</b> <b>(INCLUDES 1HR DIAGNOSTIC FEE)</b>		<b>\$1250.00</b>
		<b>TOTAL</b>		<b>\$1400.00</b>

\$

**TOTAL \$1400.00**

