

### CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY023 - 330

Date of Visit: 12/16/22

Location Address: Fort Totten

Contractor Personnel on Site:

DEEN ROWE

Work Performed: g Repair Clogged Toilet in Men's Bathroom Auger toilet and cleared

Service Calls – PO/CSS# 91198


Please take pictures and send with quote

### CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Deen Vaughn Rowe

Date: 12/16/22

Signed: 

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site.

Print Name/Rank: P COM 170

Date: 12-16-22

Signed: 

Email: PETER.J.COMPTON@GIZOARMY.MIL

