

### CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY23 MCP 10T

Date of Visit: 1/20/23

Location Address: FT TOTTEN - NY

Contractor Personnel on Site:

TITO, PAUL

Work Performed: REPAIR MCP GATE INSTALL NEW GUTTER BOLL  
PDT SYSTEM

Service Calls – PO/CSS#

CSS 91379 WO 20603

Please take pictures and send with quote

### CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: JOHN W. HARRIS

Date: 1/20/23

Signed: [Signature]

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site.

Print Name/Rank: Louis Cormo RFOS Date: 20 January 2023

Signed: [Signature]

Email: Louis.A.Cormo.CIV@Army.mil

