

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY023 - 123 (AWSA)

Date of Visit: 2/3/23

Location Address: Fort Totten

Contractor Personnel on Site:

Deen Row

Work Performed: g Replace Circulating Pump, Replace tire coupling on pump motor to restore building heat.

Service Calls - PO/CSS# 91833

Please take pictures and send with quote

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Deen Vaughn Row

Date: 2/3/23

Signed: Deen Vaughn Row

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site.

Print Name/Rank: P CORN TO

Date: 2/3/23

Signed: P CORN TO

Email: PETER.D.CORNTO.CORP@ARMY.MIL

