

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY023 - 123

Date of Visit: 2/28/23

Location Address: Fort Totten

Contractor Personnel on Site:

Deen Rowe

Work Performed: g replaced Hot Water Stem (cartridge) to stop leaking faucet
in Women's Bathroom.

Service Calls - PO/CSS#

92341


Please take pictures and send with quote

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Deenvaughn Rowe

Date: 2/28/23

Signed: 

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site.

Print Name/Rank: P CORN 30

Date: 2/28/23

Signed: 

Email: PETER.D.COMPTO.CTR.ORMY.MIL

