

### Over and Above Estimate

**Region:** 2

**Location:** NY023-206

**CSS # 92475**

**Maximo Work Order No. 21486**

**Date Issued:** 03/08/2023

**Original Description:** Building 206 tree removal next to building and main gate. Tree is falling apart and presents a danger to Soldiers, cars and can fall on main gate.

**Description of Repairs:** Remove dead tree adjacent to building. Remove all Debry and grind stump.

#### Non-Pre-Priced Estimate:

Quantity	Line Item #	Description	Labor Hours	Unit	Labor	Materials	Equipment	Total
1		Materials (See attached estimate for line items)						

*Note: RS Means (Pre-Priced) is not used in compiling this estimate.*

*Note: Subcontractor quote attached.*

#### Estimate Summary:

Labor Hours	Labor Cost	Equipment	Material	Total Cost	CE Factor	Total Estimate
Repair x5 men @ 7hrs each = 35 hours total @175.00= 3500.00	\$6125.00			\$6125.00	1.02	\$6247.5

**Please see the attached estimate.**

# ACAV SERVICES

March 8, 2023



ESTIMATE 030823 CSS92475 WO21486

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO
Customer ID#	NY023 (BLDG 206)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	3 MAR 2023
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
		<b>NY23 (BLDG 206)</b>		
		<b>REMOVE DEAD TREE ADJACENT TO BUILDING</b>		
		<b>REMOVE ALL DEBRY</b>		
		<b>GRIND STUMP</b>		
		<b><u>LABOR</u></b>		
		<b>35 HRS @ \$175.00</b>		
		<b>5 MEN 7 HRS EA</b>		
		<b>TOTAL</b>		<b>\$6125.00</b>
			<b>TOTAL</b>	<b>\$6125.00</b>

## ACAV Services

11 Snug Cove Lane  
Bayville NY 11709  
Jacka377@verizon.net  
516 941 6581

