

## Additional Funding Request

<b>Site: NY023</b>	<b>WO# 21798 CSS #93118</b>
Description of Repairs	Install a 38x84 White security cage. Build and install a x4 frame to mount the security cage on the inside of the building and paint frame.
Diagnosis: Initial Work Order	330A Rm 103 Install security cage on window. This is a physical security requirement.
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	1125.00
Additional Material Cost to Perform Repairs	445.00
Total Cost of Repair	1570.00

# ACAV SERVICES

April 22, 2023



ESTIMATE 042223 CSS93118 WO21798


Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO
Customer ID#	NY023 (330A)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A


Qty.	Item#	Description	Unit Price	Line Total
		<p><b>NY23 (330A) RM 103</b></p> <p><b>INSTALL SECURITY CAGE ON WINDOW</b></p> <p><b>INSTALL A 38WX84H WHITE SECURITY CAGE</b></p> <p><b>BUILD AND INSTALL A 2X4 FRAME TO MOUNT THE SECURITY CAGE ON THE INSIDE OF THE BUILDING PAINT FRAME</b></p> <p><b><u>MATERIAL</u></b></p> <p><b>1EA 38X84 WHITE SECURITY CAGE WITH BRACKETS</b></p> <p><b>3ES 2X4X8 LUMBER</b></p> <p><b>PAINT AND MISC HARDWAR</b></p>		

## ACAV Services

11 Snug Cove Lane  
Bayville NY 11709  
Jacka377@verizon.net  
516 941 6581

Qty.	Item#	Description	Unit Price	Line Total
		<b>TOTAL MATERIAL</b>		<b>\$445.00</b>
		<b><u>LABOR</u></b> <b>5 HRS @ 225.00 PER HR</b>		<b>\$1125.00</b>
		<b>TOTAL</b>		<b>\$1570.00</b>
				<b>TOTAL \$1570.00</b>





Room 103  
MUST GO INSIDE