

**CERTIFICATION OF WORK**  
 (To be completed by the Contractor and saved in the Contractor's CMMIS)

FACID/Building: 4/19 Bldg 206 Date of Visit: 6/2/23  
 Location Address: 85 TOTTEN NY

Contractor Personnel on Site:  
FRANK TOTO, SR.

Work Performed: REPAIR ROOM 206  
 Service Calls - PO/CSS#  
61597224 No 2221

Please take pictures and send with quote

---

**CERTIFICATION OF WORK**

To be signed by the Contractor:

Print Name: JOHN M. TOTO Date: 6/2/23  
 Signed: [Signature]

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site.

Print Name/Rank: LOUIS CORADO Date: JUNE 2, 2023  
 Signed: [Signature]  
 Email: LOUIS.A.CORADO@CIVIL.BAID.MIL

