

**CERTIFICATION OF WORK**  
(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY 13 PHOS 209 Date of Visit: 5/17/23  
 Location Address: FT TOTTEN NY

Contractor Personnel on Site:  
TITO PAUL

Work Performed: REPAIR HOLES IN ARMOR ROOM WALLS  
 Service Calls - PO/CSS#  
USC9L386 WD 22175 PO10004-1022

Please take pictures and send with quote

---

**CERTIFICATION OF WORK**

To be signed by the Contractor:

Print Name: Peter Wolke Date: 5/17/23  
 Signed: [Signature]

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site.

Print Name/Rank: PETER LANTO AFOS Date: MAY 17, 2022  
 Signed: [Signature]  
 Email: PETER.D.LANTO.CTRO@ARMY.MIL

