

## CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: N4023 /200

Date of Visit: 7/27/20

Location Address: Fort Totten

Contractor Personnel on Site:

Deenbaugh Rowe

**Work Performed:** g Closed all the valves on the baseboard heaters there should never be cold water in them if for heat only. This Service Calls – PO/CSS# is The reason there was a leak = condensation.

**Please take pictures and send with quote**

## CERTIFICATION OF WORK

**To be signed by the Contractor:**

Print Name: Deenbaugh Rowe

Date: 7/27/20

Signed: I Deenbaugh Rowe

**To be signed by Facility Manager:**

I certify that the above named individuals representing the Contractor arrived on site.

Print Name/Rank: \_\_\_\_\_ Date: \_\_\_\_\_

Signed: \_\_\_\_\_

Email: \_\_\_\_\_

