

ATTACHMENT J-0200000-05
FORMS

Over and Above Repair Work – Order Number and Description of Work Completed

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: RAMON VILLALBA

Date: 5/16/2019


Signed: 

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed:

Print Name/Rank: Vincent Giordano

Date: 5/9/19

Signed: 

E-Mail: Vincent.J.Giordano.ctr@mail.mil

ATTACHMENT J-0200000-05
FORMS

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building:

N1024

Date of Visit:

5/6/2019-5/18/2019

Contractor Personnel on Site:

BLDG 208

W.O.#

ASSET #

W.O.#

ASSET #

1. ~~3444~~ - PM-MO-9690
2. ~~3445~~ - PM-MO-9691
3. ~~3446~~ - PM-MO-9692
- ~~3633~~ - PM-QT-9689

- 3636 - PM-QT-9682
- 3637 - PM-QT-9693
- 3638 - PM-QT-9697

Work Performed:

- 3634 - PM-QT-9680
- 3635 - PM-QT-9681

Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

BLDG 209

1. PM-FOT-9697-3638

BLDG 356

BLDG 357

W.O.#

ASSET #

W.O.#

ASSET #

1. ~~3447~~ - PM-MO-9759
2. ~~3448~~ - PM-MO-9761

- 3449 - PM-MO-9766

Inspection, Testing, and Certification

1. ~~3639~~ - PM-FOT-9711
2. 3640 - PM-FOT-9712
3. 3641 - PM-FOT-9728
4. 3642 - PM-FOT-9729
- 3643 - PM-FOT-9730
- 3644 - PM-FOT-9754
- 3645 - PM-FOT-9755
- 3646 - PM-FOT-9760

Other Recurring Services

BLDG 358

1. W.O.# ASSET #
2. ~~3450~~ - PM-MO-9807
3. ~~3451~~ - PM-MO-9808
4. ~~3647~~ - PM-FOT-9778
- ~~3648~~ - PM-FOT-9779
- 3649 - PM-FOT-9790

Service Calls - Service Call Number and Description

1. ~~3650~~ - PM-FOT-9803
2. ~~3651~~ - PM-FOT-9809
3. 3652 - PM-FOT-9810