

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building:

Date of Visit: 6/21/22

Contractor Personnel on Site:

1. Deen Rowe _____ 2. _____

Work Performed:

Preventive Maintenance - (Annual, Quarterly, Monthly, equipment identification, etc.)
Service Orders -


PM/SO	WO #	Asset #	PM #	Asset Description
	17222	190917-312	PFQ190917312	1-pc Raidant Floor HeatPump
	17234	10151	PM-AN-10151	J-07 5-pc Exhaust Fan
	17235	10152	PM-AN-10152	J-07 2-pc Bathroom Exhaust Fan
	17293	10144	PM-FQT-10144	J-04 1-pc Air Handler
	17294	10145	PM-FQT-10145	J-04 1-pc Air Handler
	17295	10150	PM-FQT-10150	J-06 1-pc Fuel Oil Booster Pump for Furnace
	17381	10202	PM-QT-10202	J-57 3-pc Overhead Exhaust System
	17415	10153	PM-SA-10153	J-08 6-pc Unit Heater, Hot Water
	17416	10192	PM-SA-10192	J-49 1-pc Single Gate, Manual, Sliding Southwest
	17417	10193	PM-SA-10193	J-49 1-pc Single Gate, Manual, Swinging Southwest
	17418	10194	PM-SA-10194	J-49 1-pc Single Gate, Manual, Swinging West Entrance
	17419	10195	PM-SA-10195	J-49 1-pc Single Gate, Manual, Sliding West Entrance
	17420	10196	PM-SA-10196	J-49 1-pc Single Gate, Manual, Swinging Northwest Entrance
	17421	10197	PM-SA-10197	J-49 1-pc Double Gate, Manual, Swinging NW Entrance

CERTIFICATION OF WORK

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

To be signed by the Contractor:

Print Name: Deen Rowe Deen Rowe Date: 6/20/22

Signed: 

To be signed by Facility Manager:

Print Name/Rank: Louis A. Corzo Ros Date: 7-5-22

Signed: 

E-Mail: Louis.A.Corzo.CIV@Army.Mil