

**PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST**  
**Interior LIGHTING**

SITE AND BLDG #: NY058-02

MECHANIC  
SIGNATURE:

*Deen Rowe*

DATE: 8/16/22

LOCATION/RM #: Building 02

START TIME: 11am

FINISH TIME: 12pm

| Site Location | WO#   | Asset # | Number of lights<br>out | Size, Wattage,<br>and Type | Description      | Comments                               |
|---------------|-------|---------|-------------------------|----------------------------|------------------|--|
| NY058-02      | 18652 | IL-41   |                         |                            |                  | Interior Light in<br>Building NY058-02 |
| Oms           |       |         | 10                      | T-5                        | 4 foot           | Lift Needed                            |
| Office Area   |       |         | 2                       | T-8                        | 4 foot (ballast) |  |
|               |       |         |                         |                            |                  |  |
|               |       |         |                         |                            |                  |  |
|               |       |         |                         |                            |                  |  |
|               |       |         |                         |                            |                  |  |
|               |       |         |                         |                            |                  |  |

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency. To be performed by: General Maintenance Worker **Additional Notes:**