

## PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST

### Interior LIGHTING

SITE AND BLDG #: NY058-02

LOCATION/RM #: Building - 02

MECHANIC  
SIGNATURE:

*Deen Rowe*

DATE:

9/28/22

START TIME:

FINISH TIME:

Site Location	WO#	Asset #	Number of lights out	Size, Wattage, and Type	Description	Comments
NY058-02	18960	IL-41			Interior Light in Building NY058-02	
			12	T4, 4 ft	OMS	Lift Needed

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency. To be performed by: General Maintenance Worker **Additional Notes:**

- Ballast out
- Office Area T-8 2 bulbs
- OMS T-8 2 bulbs

