

## PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST

### Interior LIGHTING

SITE AND BLDG #: NY058-02

LOCATION/RM #: Building 02

**MECHANIC**

**SIGNATURE:** Dean Rose

**DATE:** 10/6/22

**START TIME:** 8AM

**FINISH TIME:** 9AM

Site Location	WO#	Asset #	Number of lights out	Size, Wattage, and Type	Description	Comments
NY058-02	19293	IL-41			Interior Light in Building NY058-02	
			2	T8, 4ft	Office Area	Electric Needed
			12	TS, 4ft	WMS	Lift Needed

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency. To be performed by: General Maintenance Worker **Additional Notes:**

