

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST **Interior LIGHTING**

SITE AND BLDG #: NY058-02

MECHANIC
SIGNATURE:

Deen Rowe

DATE: 12/20/22

LOCATION/RM #: Building-02

START TIME: 3:30pm

FINISH TIME: 4:30pm

Site Location	WO#	Asset #	Number of lights out	Size, Wattage, and Type	Description	Comments
NY058-02	19930	IL-41			Interior Light in Building NY058-02	
			2	4 ft T5	Office Area	Bulb last out
			2		Wong's Bathroom	On Order for Jan 7

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency. To be performed by: General Maintenance Worker **Additional Notes:**

Still Replacing OMS lights will replace next light rental.

12 still out T-5