

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST

Interior LIGHTING

SITE AND BLDG #: NY058-02

LOCATION/RM #: Building 02

MECHANIC
SIGNATURE: Deen Rowe

DATE: 2/22/23

START TIME: 930Am

FINISH TIME: 1030Am

Site Location	WO#	Asset #	Number of lights out	Size, Wattage, and Type	Description	Comments
NY058-02	20748	IL-41			Interior Light in Building NY058-02	
			20	78, 4ft	OMS (Vehicle Bay)	Lift Needed

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency. To be performed by: General Maintenance Worker **Additional Notes:**

-Ballast is out above desk in main office.

