

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST
Interior LIGHTING

SITE AND BLDG #: NY058-03

LOCATION/RM #: 8.03

MECHANIC
SIGNATURE:

Deen Lowe

DATE: 2/14/23

START TIME:

2pm

FINISH TIME:

230 pm

Site Location	WO#	Asset #	Number of lights out	Size, Wattage, and Type	Description	Comments
NY058-03	20749	IL-42			Interior Light in Building NY058-03	
		-				

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency. To be performed by: General Maintenance Worker **Additional Notes:**

No Power in Building 03

