

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST

Interior LIGHTING

SITE AND BLDG #: NY058-07

LOCATION/RM #: Building 07

MECHANIC
SIGNATURE: Dean Rose

DATE: 8/18/21

START TIME: 9Am

FINISH TIME: 9:15 Am

| Site Location | WO# | Asset # | Number of lights out | Size, Wattage, and Type | Description | Comments |
|---------------|-------|---------|----------------------|-------------------------|-------------------------------------|----------|
| NY058-07 | 18656 | IL-45 | | | Interior Light in Building NY058-07 | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency. To be performed by: General Maintenance Worker **Additional Notes:**

All lights good

