

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building:

Date of Visit: 7/15/22

Contractor Personnel on Site:

1. Deen Rowe _____ 2. _____

Work Performed:

Preventive Maintenance - (Annual, Quarterly, Monthly, equipment identification, etc.)
Service Orders -

PM/SO	WO #	Asset #	PM #	Asset Description
	17708	10298	PM-AN-10298	J-26 1-pc Kitchen Sink, Double Basin, Countertop RM 142
	17709	10299	PM-AN-10299	J-26 1-pc Kitchen Hand Wash Sink Rm 142
	17710	10300	PM-AN-10300	J-26 1-pc Kitchen Sink, Triple Basin, Countertop RM 141
	17711	10301	PM-AN-10301	J-26 2-pc Garbage Disposal RM 141
	17712	10302	PM-AN-10302	J-26 1-pc Kitchen Sink, Single Basin, Countertop (W/ Wells Circulating Pump) RM 141
	17713	10303	PM-AN-10303	J-26 1-pc Dish Washer RM 141
	17714	10304	PM-AN-10304	J-26 6-pc Lavatory, Countertop RM 136
	17715	10305	PM-AN-10305	J-26 5-pc Toilet, Flush Valve, Wall Mounted RM 136
	17716	10306	PM-AN-10306	J-26 5-pc Urinal, Wet, Flush Valve RM 136
	17717	10307	PM-AN-10307	J-26 11-pc Shower, Built-In RM 134
	17718	10308	PM-AN-10308	J-26 6-pc Lavatory, Countertop RM 138
	17719	10309	PM-AN-10309	J-26 7-pc Toilet, Flush Valve, Wall Mounted RM 138
	17720	10310	PM-AN-10310	J-26 6-pc Shower, Built-In RM 140
	17721	10311	PM-AN-10311	J-26 3-pc Toilet, Flush Valve, Wall Mounted RM 221
	17722	10312	PM-AN-10312	J-26 3-pc Urinal, Wet, Flush Valve RM 221
	17723	10313	PM-AN-10313	J-26 3-pc Lavatory, Countertop RM 221

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

	17724	10314	PM-AN-10314	J-26 5-pc Toilet, Flush Valve, Wall Mounted RM 222
	17725	10315	PM-AN-10315	J-26 4-pc Lavatory, Countertop RM 221
	17726	10316	PM-AN-10316	J-26 1-pc Kitchen Sink, Double Basin, Countertop RM 219
	17727	10317	PM-AN-10317	J-26 1-pc Kitchen Sink, Double Basin, Countertop RM 211
	17728	10318	PM-AN-10318	J-26 1-pc Janitor Sink, Floor Mounted Rm 224
	17729	10319	PM-AN-10319	J-26 1-pc Janitor Sink, Floor Mounted Rm 137
	17730	10320	PM-AN-10320	J-26 1-pc Kitchen Sink, Double Basin, Countertop Rm 103
	17731	10321	PM-AN-10321	J-26 2-pc Garbage Disposal RM 141
	17732	10322	PM-AN-10322	J-26 1-pc Drinking Fountain Corridor 130
	18065	10335	PM-MO-10335	J-45 4-pc Double Light, Pole Mounted Military Equipment Parking
	18066	10336	PM-MO-10336	J-45 10-pc Motor Vehicle Area Light Military Equipment Parking
	18067	10342	PM-MO-10342	J-49 1-pc Single Gate, Automatic, Sliding Site Entrance
	18098	10261	PM-SA-10261	J-14 1-pc Dehumidifier
	18099	10344	PM-SA-10344	J-52 1-pc Overhead Door, Steel, Roll Up, 12Wx14H
	18100	10346	PM-SA-10346	J-56 1-pc Fire Door Kitchen
	18210	190917-320	PMQ190917320	165-pc Interior Lights 4 Florescent

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Deen Rowe D. Rowe Date: 7/15/22

Signed: Deen Rowe

To be signed by Facility Manager:

Print Name/Rank: P. G. Smith Date: 7.13.22

Signed: P. G. Smith

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

E-Mail: PETER&NNKDESIGN.COM