

Liability work noted below completed 2/25/2022

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST

Interior LIGHTING

SITE AND BLDG #: NY058-104

MECHANIC
SIGNATURE: DEEN LOWE

DATE: 2/22/22

LOCATION/RM #: Building 104

START TIME: 11Am

FINISH TIME: 1pm

Site Location	WO#	Asset #	Number of lights out	Size, Wattage, and Type	Description	Comments
NY058-104	15864	190917-320		165-pc Interior Lights 4 Flourescent		

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency. To be performed by: General Maintenance Worker **Additional Notes:**

Men's Bathroom 1st floor — 3 ballast out

1st floor Hallway — 1 ballast out

Main Hallway — 3 light fixtures out.

Unit common 109 — 2 ballast out.



