

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST

Interior LIGHTING

SITE AND BLDG #: NY058-104

MECHANIC
SIGNATURE: Den Lowe

DATE: 7/14/21

LOCATION/RM #: Building 104

START TIME: 12pm

FINISH TIME: 2pm

Site Location	WO#	Asset #	Number of lights out	Size, Wattage, and Type	Description	Comments
NY058-104	18659	IL-48			Interior Light in Building NY058-104	

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency. To be performed by: General Maintenance Worker **Additional Notes:**

- 24 T8 lights out in Assembly, lift or very tall ladder needed.
- Outside Assembly (143) light sensor not working
- Still replacing ballast

