

## PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST

### Interior LIGHTING

SITE AND BLDG #: NY058-104

LOCATION/RM #: Building 104

MECHANIC  
SIGNATURE: DEEN ROWE

DATE: 9/29/22

START TIME: 12pm

FINISH TIME: 4pm

Site Location	WO#	Asset #	Number of lights out	Size, Wattage, and Type	Description	Comments
NY058-104	18967	IL-48			Interior Light in Building NY058-104	

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency. To be performed by: General Maintenance Worker **Additional Notes:**

*In Process of Changing Lights and Ballast will be done by*

*10/31/22*

CM

- \* Electrician Needed For Lights above main entrance
- \* Also motion sensor outside Assembly (143) is not working needs to be replaced.