

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST **Interior LIGHTING**

SITE AND BLDG #: NY058-104

**MECHANIC
SIGNATURE:**

DATE:

LOCATION/RM #:

START TIME:

FINISH TIME:

Site Location	WO#	Asset #	Number of lights out	Size, Wattage, and Type	Description	Comments
NY058-104	19937	IL-48			Interior Light in Building NY058-104	
			2	T-8 4ft	1st floor cubicle	ballast out
			12	unknown	Hallway Ceiling lights	Electrician needed / 1.1 ft
			2	T-8 4ft	1st floor Hallway	ballast out

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency. To be performed by: General Maintenance Worker **Additional Notes:**

1 Motion Sensor out in Hallway between cages and 143 assembly

