

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST

Interior LIGHTING

SITE AND BLDG #: NY058-104

MECHANIC
SIGNATURE: *Dean Rane*

DATE: 2/15/23

LOCATION/RM #: Building 104

START TIME: 2pm

FINISH TIME: 4pm

Site Location	WO#	Asset #	Number of lights out	Size, Wattage, and Type	Description	Comments
NY058-104	20755	IL-48			Interior Light in Building NY058-104	

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency. To be performed by: General Maintenance Worker **Additional Notes:**

- light sensor in hallway (Assembly 143) is out (electrician needed)
- three ballast are out
- Room 147 (supply office) light switch not working - will replace.

