

## CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY058 Date of Visit: 07/07/2020

Location Address: \_\_\_\_\_

Contractor Personnel on Site:

Deen Rowe

**Work Performed:** After initial work completed as FFP, found condensate pump motor is sticking and needs replace Please issue new CSS Ticket

**Service Calls – PO/CSS# CM From 25826**

**Please take pictures and send with quote**

## CERTIFICATION OF WORK

**To be signed by the Contractor:**

Print Name: Deen Rowe Date: 07/07/2020

Signed: Deen Rowe

**To be signed by Facility Manager:**

I certify that the above named individuals representing the Contractor arrived on site.

Print Name/Rank: \_\_\_\_\_ Date: \_\_\_\_\_

Signed: \_\_\_\_\_

Email: \_\_\_\_\_

# WORK ORDER ESTIMATE

CSS #:

25894

Work Order #:

Urgent

Emergency

Urgent

2

Routine

Company Name:	ISG	Facility ID:	NY058
Contractor POC:			
Telephone No:		Building/Location; (e.g., Classroom/Room #)	OMS
E-Mail Address:			
Assigned Technician(s):	Deen Rowe		

## DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

7/7 Completed original call on FFP, while on site performing PM it was found that Condensate Pump needs to be replaced, it got stuck again but is working right now after a few taps to the motor. System needs a new condensate pump.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Labor			6	\$480.00
Condensate Pump				\$300.00
				\$0.00
				\$0.00
SUB-TOTAL COSTS:	Materials Total	\$300.00	Labor	\$480.00
	TOTAL			\$780.00