

Additional Funding Request

Site: NY023	WO# 7684 CSS # 27692 Asset# 10260
Description of Repairs	Asset#10260, both glycol feed tanks need to be chemically changed out
Diagnosis: Initial Work Order CSS# 27692	Replace 35 Gallons of Glycol, to include disposal of defective material
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	3 hrs @ 185.00 = \$255.00
Additional Material Cost to Perform Repairs	\$1945.00
Total Cost of Repair	\$2500.00

ACAV SERVICES

November 20, 2020



ESTIMATE 112020 CSS27692

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RD DPW R Linn
Customer ID#	NY058 (OMS BLDG)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty	Item #	Description	Unit Price	Line Total
1	1	NY058 OMS BUILDING REPLACE 35 GAL OF GLYCOL DISPOSE OF DEFECTIVE MATERIAL MATERIAL 35 GAL OF NU-CALGON PROPYLENE BLUE GLYCOL -76 TO 360 DEGREES F 6EA 5GAL CONTAINERS \$308.40 EACH (30GAL) LABOR 3HRS @ \$185.00 PER HOUR		\$1945.00
				\$555.00
		TOTAL		\$2500.00

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581