

## Additional Funding Request

<b>Site: NY0058</b>	<b>WO# 11482 CSS # 28351</b>
Description of Repairs	Remove and Replace 35 gal of glycol and dispose of defective material.
Diagnosis: Initial Work Order	Replace Glycol in the AC system on the 2nd floor machine room Main Building. Can be done in the spring before the AC is turned on
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	3hrs @ \$183.33= \$550.00
Additional Material Cost to Perform Repairs	\$1950.00
Total Cost of Repair	\$2500.00

# ACAV SERVICES

January 28, 2021



ESTIMATE 012821 CSS28351

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RD DPW R Linn
Customer ID#	NY058 (OMS BLDG)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty	Item #	Description	Unit Price	Line Total
1	1	NY058 MAIN BUILDING 2 <sup>ND</sup> FLOOR MECHANICAL AREA REPLACE 35 GAL OF GLYCOL DISPOSE OF DEFECTIVE MATERIAL MATERIAL 35 GAL OF NU-CALGON PROPYLENE BLUE GLYCOL -76 TO 360 DEGREES F 6EA 5GAL CONTAINERS \$308.40 EACH (30GAL) LABOR 3HRS @ \$185.00 PER HOUR		\$1950.00
		TOTAL		\$550.00
				\$2500.00

## ACAV Services

11 Snug Cove Lane  
Bayville NY 11709  
Jacka377@verizon.net  
516 941 6581