

Additional Funding Request

Site: NY058	WO# 19769 CSS #90631
Description of Repairs	Replace Defective Relief valve on water Tank 2
Diagnosis: Initial Work Order	Trouble shoot hot water tank #2, Pressure release valve
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	6 hrs @ 250.00= 1500.00
Additional Material Cost to Perform Repairs	675.00
Total Cost of Repair	2175.00

ACAV SERVICES

November 4, 2022



ESTIMATE 110422C CSS90631 WO19769

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RD DPW L CORBO
Customer ID#	NY058 (MAIN BLDG)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item #	Description	Unit Price	Line Total
1	1	NY058 MAIN BLDG (2ND FLOOR)		
		REPLACE DEFECTIVE RELIEF VALVE ON WATER TANK #2		
		<u>MATERIAL</u>		
		1EA WATTS 3/4" LLL40XL T&P RELIEF VALVE		\$675.00
		<u>LABOR</u>		
		6 HRS @ \$250.00 PER HOUR		\$1500.00
		TOTAL		\$2175.00

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581

3/4" LLL40XL T&P Relief Valve, Lead Free (150 psi)

Brand: **Watts**

SKU: **0163803**

☆☆☆☆☆ (0)

Q&A: (0)



