

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: N4058 - 104

Date of Visit: 12/29/22

Location Address: Shoreham, Long Island

Contractor Personnel on Site:

DEEN ROWE

Work Performed: g Manually opened valve on each VAV return line, to allow
hot water through coils. Cubicle Area now has heat.
Service Calls – PO/CSS# 91326


Please take pictures and send with quote

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Deen Vaughn Rowe

Date: 12/29/22

Signed: 

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site.

Print Name/Rank: P COM 100

Date: 12-29-22

Signed: 

Email: PETER.J.COMITO@CIZ.BARMY.MIL

