

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: N405B - 104

Date of Visit: 4/24/23

Location Address: Shoreham, Long Island

Contractor Personnel on Site:

Deen Rowe

Work Performed: Replaced condensate pump for AC in Electrical Room, New pump has bigger discharge so the piping was redone to accommodate.

Service Calls - PO/CSS# 93068


Please take pictures and send with quote

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Deenvaughn Rowe

Date: 4/24/23


Signed: 

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site.

Print Name/Rank: SEAN MCBRIN

Date: 4/26/23

Signed: 

Email: Sean.McBain.cfr@army.mil




WARNING

READ OF ELECTRICAL SAFETY: DO NOT TOUCH ANY PARTS OF THE UNIT OR THE WIRING. DISCONNECT ALL POWER SOURCES BEFORE ATTEMPTING TO REPAIR OR MAINTAIN THE UNIT.



ADVERTISSEMENT

AVERTISSEMENT: LIREZ ATTENTION AUX PARTIES VIBRANTES DE L'APPAREIL. DÉBRANCHEZ TOUS LES ALIMENTATIONS ÉLECTRIQUES AVANT D'ESSAYER DE RÉPARER L'APPAREIL.



3/4 AMP
BUSSMANN

tyco
P & B
7E166
003 Taiwan 1012

P25-1

DALLAS
DS12C887
0822L 365633
PHILIPPINES

REAL TIME
DS12C887

REV 1.0
LIEBERT
166736
GAD9



LIEBERT
ASSY NO. 415761C.1
REV 34
EMERSON NETWORK POWER

IMN0357
ASSY IN TRAY

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100

REV 312004

