

Master Plumber Lic. 1378
NYC Oil Burner Lic. 2711
Home Improvement Lic. 0809217
N.Y. Certified Back Flow Prevention Lic. 921
DANIEL D. VESSIO



Boiler & Burner
Oil & Gas & AC
Sales & Service
Residential, Commercial and Industrial
High Pressure Specialists

119-02 23RD AVENUE
COLLEGE POINT, NY 11356-0246

September 24, 2019 TEL: (718) 459-1223 • FAX (718) 445-0936

Since 1939

www.nulite-ny.com

RE: U.S. ARMY

SHOREHAM, NY

To whom it my concern:

I visually inspected the following boilers in compliance with NYC Local Law 62/91, New York State Sec 204 of NYS Labor Law and The National Fuel Code. The boilers and the boiler rooms were visually inspected to be code compliant and condition evaluated. This inspection did not include any performance testing.

MAIN BUILDING:

5 Boilers ...Slant Fin boilers model # TR-70 WU

All boilers are code compliant; boiler room is code compliant.

Condition Good.

ANNEX BUILDING:

(REPAIR SHOP)

2 Boilers...Slant Fin boilers model # TR-70 WU

All boilers are code compliant ; boiler room is code compliant.

Condition Good.

Total boilers inspected 7.

Respectfully,

Daniel D. Vessio



CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: N4058

Date of Visit: 9/25/19

Contractor Personnel on Site:

1. J WORME

2. D VESFO

Work Performed:

Preventive Maintenance -(Annual, Quarterly, Monthly, equipment identification, etc.)
Service Orders -

Asset #	Qty	Asset Description
		INSPECTED 5 OIL Burners
		IN MAIN Bldg.
		INSPECTED 2 OIL Burners
		IN SHOP Bldg.

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: J Worme

Date: 9/25/19

Signed: [Signature]

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed:

Print Name/Rank: ROBERT BENNET


Date: 9/15/16

Signed: [Signature]


E-Mail: _____



NY058 MASH Bldg




NY058 MASH Bldg




NY058 MASH Bldg



NY058 MASH Bldg



NY058 MASH Bldg



NY058 MASH Bldg



NY058 MASH Bldg



NY058 MASH Bldg



NY058 MASH Bldg




NY058 MASH Bldg



NY058 MASH Bldg



NY058 MASH Bldg



NY058 MASH Bldg