

**CERTIFICATION OF WORK  
SERVICE CALL**

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY070 Date of Visit: 1/17-18, 1/24-25, 2/1, 2/2/24

Contractor Personnel on Site:

- |                        |          |
|------------------------|----------|
| 1. <u>Charles Dowd</u> | 4. _____ |
| 2. <u>Dan Flynn</u>    | 5. _____ |
| 3. _____               | 6. _____ |

**Service Call Number**

CSS# 95244 WO# 14093

**Description of Repairs**

1. Replace (4) AHU damper actuators in TB
2. Integrate (4) transfer fans into control system in TB
3. Replace workbay ventilation gas sensor cartridges in OMS
4. Replace workbay ventilation panel LCD readouts in OMS
5. Replace ERV current switch/ relay in OMS
6. Replace non-communicating ERV EF VFD

**CERTIFICATION OF WORK**

To be signed by the Contractor:

Print Name: Charles Dowd Date: 2/9/24

Signed: Charles Dowd

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: John F. Granata AFOS Date: 02/12/2024

Signed: John F. Granata

E-Mail: john.f.granata.ctr@army.mil