



Proposal

CMI Management
Mr. Joe Bayne
5285 Shawnee Rd
Alexandria, VA. 22312

Sep 5, 2022

RE: Urinal repair NY116
W/O18280
CSS# 1644

- Service Call	
- Repair urinal in mens room	
- Replace sloan flush valve assembly	
	4hrs labor x120.00 480.00
(1) Granger 4THJ7 Brass spud assembly	20.71
(2) Granger.611R71 Sloan valve assembly	266.70
20%mat mark up.	57.48

Total Due \$824.89