



PROPOSAL - CONTRACT

CMI Management
Mr. Joe Bayne
5285 Shawnee Rd.
Alexandria, VA. 22312

May 18, 2020

RE:New Windsor CSS24993 NY116
WO 8230
Commode Repair

- Rebuild (1) commode flushometers
- Disassemble and clean mineral deposits from valve bodie.
- Install Repair/seal & diaphragm kits
- Install vacuum breaker assemblies

1 Sloan rebuild & seal kit.	.	56.50.	56.50
-----------------------------	---	--------	-------

sub total	56.50
7% tax.	3.96

	60.46

4hrs @120.00	480.00
--------------	--------

sub total.	540.46
20% profit/OH.	108.09.

Total.	648.55

701 Randall Rd Ballston Spa, NY 12020 TEL 518-441-6003 FAX 518-399-5440

Email rdpostulka@verizon.net

INDUSTRIAL

COMMERCIAL

INSTITUTIONAL