



# Invoice

CMI Management  
Mr. Joe Bayne  
5285 Shawnee Rd  
Alexandria VA. 22312

April 29, 2021

RE: NY116 CSS29530

- Replace (1) commode flushometer assembly
- Install brass spud on commode and urinal
- Replace siezed shutoff valve on urinal
- Disassemble and clean mineral deposits from valve bodie.
- Install Repair/seal & diaphragm kit
- Install vacuum breaker assembly

|                             |            |         |
|-----------------------------|------------|---------|
| 1 Sloan rebuild & seal kit. | 56.50.     | 56.50   |
| 1 Brass spud                | 17.65.     | 17.65   |
| 1 sloan valve assembly      |            | 220.44  |
| 1 3/4 shutoff valve         |            | 71.50   |
|                             |            | -----   |
|                             | sub total  | 366.09  |
|                             | 7% tax.    | 25.63   |
|                             |            | -----   |
|                             |            | 391.72  |
|                             |            |         |
| 6hrs @120.00                |            | 720.00  |
|                             |            | -----   |
|                             | sub total. | 1111.72 |
| 20% profit/OH.              |            | 222.34  |
|                             |            | -----   |
|                             | Total.     | 1334.06 |

701 Randall Rd Ballston Spa, NY 12020 TEL 518-441-6003 FAX 518-399-5440

Email [rdpostulka@verizon.net](mailto:rdpostulka@verizon.net)

INDUSTRIAL

COMMERCIAL

INSTITUTIONAL