



Proposal

CMI Management
Mr. Joe Bayne
5285 Shawnee Rd
Alexandria, VA. 22312

Jul 24, 2022

RE: Toilet repair NY116
W/O18281
CSS# 1646

- Service Call
- Repair toilet in mens room
- Replace sloan flush valve assembly

4hrs labor x120.00 480.00

(1) Granger 4THJ7 Brass spud assembly	20.71
(1) Granger.611M51 Sloan valve assembly	299.42

20%mat mark up.	64.03
-----------------	-------

Total Cost	\$864.16
------------	----------