



PROPOSAL - CONTRACT

CMI Management
Mr. Joe Bayne
5285 Shawnee Rd.
Alexandria, VA. 22312

May 18, 2020

RE:Saugerties CSS#25071 NY128
Commode/ Sink Repairs

- Rebuild (1) commode flushometers
- Disassemble and clean mineral deposits from valve bodie.
- Install Repair/seal & diaphragm kits
- Install vacuum breaker assemblies
- Install brass spud on water closet
- Replace el595 sensor

1 Sloan rebuild & seal kit.	56.50.	56.50
1 Brass spud	17.65.	17.65
1 el595 Sensor kit		294.91
1 450 v sloan lav sensor control.		172.00
1 ETF 370 a elc valve (lav).		110.50

	sub total	651.56
	7% tax.	45.61

		697.17
8hrs @120.00		960.00

	sub total.	1657.17
20% profit/OH.		331.43.

	Total.	1988.60

701 Randall Rd Ballston Spa, NY 12020 TEL 518-441-6003 FAX 518-399-5440

Email rdpostulka@verizon.net

INDUSTRIAL

COMMERCIAL

INSTITUTIONAL



INDUSTRIAL

COMMERCIAL

INSTITUTIONAL