



Proposal

CMI Management
Mr. Joe Bayne
5285 Shawnee Rd
Alexandria VA. 22312

March 1, 2021

RE: NY116 CSS29530

- Replace (1) commode flushometer assembly
- Install brass spud on commode and urinal
- Replace siezed shutoff valve on urinal
- Disassemble and clean mineral deposits from valve bodie.
- Install Repair/seal & diaphragm kit
- Install vacuum breaker assembly

1 Sloan rebuild & seal kit.	56.50.	56.50
1 Brass spud	17.65.	17.65
1 sloan valve assembly		220.44
1 3/4 shutoff valve		71.50

	sub total	366.09
	7% tax.	25.63

		391.72
	6hrs @120.00	720.00

	sub total.	1111.72
	20% profit/OH.	222.34

	Total.	1334.06

701 Randall Rd Ballston Spa, NY 12020 TEL 518-441-6003 FAX 518-399-5440

Email rdpostulka@verizon.net

INDUSTRIAL

COMMERCIAL

INSTITUTIONAL