



PROPOSAL

CMI Management
Mr. Joe Bayne
5285 Shawnee Rd.
Alexandria, VA. 22312

September 9, 2020

RE: CSS26259 NY128
WO 10234
Commode/Sink Repair

- Rebuild (1) commode flushometers
- Disassemble and clean mineral deposits from valve bodie.
- Install Repair/seal & diaphragm kits
- Install vacuum breaker assemblies

1 Sloan rebuild & seal kit. 9(toilet)	56.50.	56.50
1 Sloan EAF-275 Faucet assembly (Granger 5YJP4).	702.00.	702.00

	sub total	758.50
	7% tax.	53.10

		811.60
2 trips to facility 8hrs @120.00		960.00

	sub total.	1771.60
	20% profit/OH.	354.32.

	Total.	2125.92

701 Randall Rd Ballston Spa, NY 12020 TEL 518-441-6003 FAX 518-399-5440

Email rdpostulka@verizon.net

INDUSTRIAL

COMMERCIAL

INSTITUTIONAL