



PROPOSAL - CONTRACT

CMI Management
Mr. Joe Bayne
5285 Shawnee Rd.
Alexandria, VA. 22312

June 14, 2020

RE:Saugerties CSS#25198 NY128
Commode WO8691

- Rebuild (1) commode flushometers
- Disassemble and clean mineral deposits from valve bodie.
- Install Repair/seal & diaphragm kits
- Install vacuum breaker assemblies
- Install brass spud on water closet

1 Sloan rebuild & seal kit.	56.50.	56.50
1 Brass spud	17.65.	17.65

sub total	74.15
7% tax.	5.19

79.34

4hrs @120.00	480.00
--------------	--------

sub total.	559.34
20% profit/OH.	111.87

Total.	671.21
--------	--------

701 Randall Rd Ballston Spa, NY 12020 TEL 518-441-6003 FAX 518-399-5440

Email rdpostulka@verizon.net

INDUSTRIAL

COMMERCIAL

INSTITUTIONAL