EMTech
Energy Management Technologies, LLC
Service 518-631-6004   Main 518-783-7810   Fax 518-783-2079

7196

FIELD REPORT

Location Name / Address	Bill To	Date
Salvation Army		9-22-21
Contact / Phone	**EMTech Contract #**	**Customer PO #**
	Technician Code	
	☐ Contract ☒ T & M ☐ Quoted ☐ Warranty ☐ Sales Support ☐ Material Sale Only	

Problem Description:

JOBSITE SAFETY CHECKLIST
- ☐ Electrical Shock Hazards
- ☐ Confined Space
- ☐ Inadequate Ventilation
- ☐ Water/Oil/Other Liquids on Floor
- ☐ Trip or Fall Hazards
- ☐ Fire or Explosive Hazards
- ☐ Site Checked

WORK PERFORMED

MOTOR POOL BLDG
Replaced Flame Rod + Spark Rod at both Boilers 3FH
Boiler #4 Loch "Knight" needs fire box cleaned.
Checked all safetys, pumps & valves.

MAN BLDG. 3 DOM H.W. Boilers ops Normal

REFRIGERANT ACTIVITY

Did Refrigerant Activity occur?
- ☐ Yes   If yes, a Refrigerant Activity
- ☐ No   Report Must be completed

SERVICE EXPENSE

PARTS. MATERIAL SOURCE
- ☐ CS Customer Supplied
- ☐ PC Procurement/Cash
- ☐ TS Truck
- ☐ TP EMTech Parts
- ☐ VP Vendor Purchase

PARTS and MATERIAL

Source	Qty	Part #	Description	PO #
VP	2	Flm Snsr Kit w/ Gasket		
VP	2	Ign Kit w/ Gasket		
VP	1	Gasket Kit Bnr		

EXPENSE TYPE (CHECK ALL THAT APPLY)
- ☐ Sm Recovery Sys
- ☐ Lg Recovery Sys
- ☐ Vacuum Pump
- ☐ Welder
- ☐ Tube Brush Unit
- ☐ Technology Charge
- ☐ Fuel Charge
- ☐ Environment Fee
- ☐ Trip Charge
- ☐ Pressure Washer
- ☒ Mileage
- ☒ Misc. Supplies

LABOR

Date	Name	DDC (Tech)	MS (Mech)	MS (Chiller)	Reg	Over Time	Double Time
9-22-21	Mike		X		5		

Follow-up Required? ☐ Yes ☐ No Describe

Customer Signature	Date	PO #
	9-22-21	

Services described were performed as part of the terms of this document