

# PREVENTIVE MAINTENANCE PROGRAM CHECKLIST

FILTER CHANGE ONLY

SITE AND BLDG#: NY023-123

MECHANIC

SIGNATURE: SIGNATURE ON FILE (DROWE)

DATE: 4/5/23

Site Location	WO#	Asset#	PM#	Manufacturer	Model Number	Serial#	Asset Description	Asset Location
NY023-123	2-21496	9356	FA-9356	SAYLOR BEALL	707	7-10-M06	J-20 1-PC Air Compressor, 9356, NY023-123	

CHECK POINT	CHECKPOINT DESCRIPTION	NOTES/ACTIONS
		(if Task Complete is Checked 'NO', Then Provide Explanation)
TO BE PERFORMED AT EACH INSPECTION SERVICE		
	Change filter	

**Note:** The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency.

**To be performed by:** General Maintenance Worker

**Additional Notes:**

- duplicate work order this asset is already complete there is only one air compressor in building 123